09-50026ang1:120m12726t13-JNFitect-07/34/14-4 1 ნო ternel ტუ/31/14-41 1 ნო te

UNITED STATES DISTRICT COURT SOUTHERN DISTRICT OF NEW YORK

.....

IN RE:

GENERAL MOTORS LLC IGNITION SWITCH LITIGATION 14-MD-2543 (JMF)

This Document Relates To

Case No.

PAMELA EDWARDS, INDIVIDUALLY AND AS REPRESENTATIVE OF THE ESTATE OF PAUL EDWARDS Together with all individuals whose names appear on the attached Exhibit "A"

PLAINTIFFS,

Complaint

Jury Trial Demanded

v.

GENERAL MOTORS, LLC

DEFENDANT.

.....

PLAINTIFFS' MOTION FOR LEAVE TO FILE OMNIBUS COMPLAINT WITH THE MDL COURT

Pursuant to Fed. R. Civ. Pro 42(a), Plaintiffs hereby respectfully request that the Court grant them leave to file an Omnibus Complaint, a copy of which is attached hereto as Exhibit "1," and in support thereof state as follows:

Plaintiffs assert claims against General Motors, LLC (hereafter referred as "New GM") under various theories of liability.

On July 9, 2014 the Judicial Panel on Multidistrict Litigation ordered the consolidation of all related actions pursuant to 28 U.S.C. § 1407. Plaintiffs now seek this Court's permission to file an Omnibus Complaint for Plaintiffs for pre-sale injuries and deaths in this proceeding in order to assist the Court in the orderly organization and efficient pre-trial disposition of these matters. The Omnibus Complaint alleges that New GM is liable for the wrongful deaths and

personal injuries that Plaintiffs suffered before the closing date of the sale of General Motors Corporation.

Because the Firms are aware and mindful of the sale order, the plan injunction, and the various stay stipulations as well as the many outstanding and pending issues identified in Judge Gerber's July 30th DECISION WITH RESPECT TO NO STAY PLEADING (PHANEUF PLAINTIFFS) and cautious as to the potential and substantial effect many of Judge Gerber's future rulings will likely have on the Plaintiffs' claims contained herein, this relief is requested at this time to make this Court—and by simultaneous filings in the bankruptcy proceeding—Judge Gerber, aware of the significant number of pre-sale death and injury claims caused by defective ignition switches. The right to be heard on those pending issues in Judge Gerber's court (only in the unlikely event that Designated Counsel does not "satisfactorily present the others' views . . . ") is an important right to these Plaintiffs, and is hereby preserved. Neither the Firms nor the Plaintiffs that would be covered by the Omnibus Complaint intend to take any step in the MDL proceeding or otherwise that is not explicitly permitted by this MDL Court by way of a Courtissued case management order. The Omnibus Complaint would move apace with the other actions in the MDL proceeding and be subject to any orders of the bankruptcy court on the threshold issues the same as any other litigant or claimant.

Plaintiffs expect they will be entering into a Stay Stipulation as to the claims set out in the Complaint during the pendency of the orderly and coordinated process ongoing in the Bankruptcy Court which Plaintiffs believe will assure the fair adjudication of important issues. The careful and coordinated disposition of dispositive issues is paramount and, as Judge Gerber rightly opines, should be done in a thoughtful, collaborative and systematic fashion.

Other than the filing of the Omnibus Complaint in the MDL proceeding, no other relief is sought by this Motion for Leave.

Respectfully Submitted,

HILLIARD MUÑOZ GONZALES LLP

By: /s/ Robert C. Hilliard

Robert C. Hilliard State Bar No. 09677700 Federal ID No. 5912 bobh@hmglawfirm.com Rudy Gonzales, Jr. State Bar No. 08121700 Federal ID No. 1896 rudyg@hmglawfirm.com Catherine D. Tobin State Bar No. 24013642 Federal ID No. 25316 catherine@hmglawfirm.com Marion Reilly Texas Bar No. 24079195 Federal ID No. 1357491 marion@hmglawfirm.com

719 S. Shoreline Boulevard, Suite 500 Corpus Christi, TX 78401 Telephone No.: (361) 882-1612 Facsimile No.: (361) 882-3015

-and-

By: /s/ Thomas J. Henry

Thomas J. Henry State Bar No. 09484210 Federal ID No. 12980 tjh@tjhlaw.com Curtis W. Fitzgerald, II State Bar No. 24012626 Federal ID No. 24980 cfitzgerald@tjhlaw.com

THOMAS J. HENRY INJURY ATTORNEYS 521 Starr St.

Corpus Christi, Texas 78401 Telephone No.: (361) 985-0600 Facsimile No.: (361) 985-0601

ATTORNEYS FOR PLAINTIFFS

CERTIFICATE OF SERVICE

I HEREBY CERTIFY that on July 31, 2014, I filed the foregoing document with the Clerk of Court via the CM/ECF system, which will automatically serve and send email notification of such filing to all registered attorneys of record.

/s/ Robert C. Hilliard Robert C. Hilliard

EXHIBIT "1"

UNITED STATES DISTRICT COURT
SOUTHERN DISTRICT OF NEW YORK

.....

IN RE:

GENERAL MOTORS LLC IGNITION SWITCH LITIGATION 14-MD-2543 (JMF)

This Document Relates To

Case No.

PAMELA EDWARDS, INDIVIDUALLY AND AS
REPRESENTATIVE OF THE ESTATE OF PAUL EDWARDS
Together with all individuals whose names
appear on the attached Exhibit "A"
PLAINTIFFS,

Complaint

Jury Trial Demanded

v.

GENERAL MOTORS, LLC

DEFENDANT.

OMNIBUS COMPLAINT FOR PRE-SALE PERSONAL INJURIES AND DEATHS

COME NOW the individuals listed on the attached and fully incorporated Exhibit A (hereinafter "Named Plaintiffs"), through undersigned counsel, respectfully represent that:

PRELIMINARY STATEMENT

- 1. The Named Plaintiffs' causes of action are brought solely against GENERAL MOTORS, LLC ("New GM"). Plaintiffs do not assert any causes of action against General Motors Corporation ("Old GM").
- 2. Any references to General Motors Corporation, Old GM, or pre-sale order conduct in this Complaint are for background and reference purposes only. That is, under the June 26, 2009 Amended and Restated Master Sale and Purchase Agreement wherein New GM acquired certain Old GM assets, New GM acquired knowledge of Old GM's activities and the defective ignition switch via the minds of the employees, officers and managers it acquired

through the sale order. New GM also acquired knowledge of Old GM's activities and the defective ignition switch via the books and records obtained and/or acquired as a result of the sale order. Thus, the duties of Old GM are part of the foundation for New GM's liability. Additionally, New GM's liability for damages is attributable to its own post-sale conduct.

II. INTRODUCTION

3. At any given moment, an ignition switch in a wide variety of General Motors vehicles could fail, killing or maiming countless individuals. The disastrous system failures in GM vehicles are triggered by something as simple as a key chain on the vehicle's key or a bump in the road, as the ignition switch shifts from the "run" position into the "accessory/off" position, with a corresponding reduction or loss of power. See March 11, 2014 Letter from New GM to Ms. Nancy Lewis re: NHTSA Recall No. 14V-047, at 1 ("Until the recall repairs have been performed, it is very important that customers remove all items from their key rings, leaving only the vehicle key."); see also New GM Safety Recall Notice ("Th[e] risk increases if your key ring is carrying added weight (such as more keys or the key fob) or your vehicle experiences rough road conditions or other jarring or impact related events."). Yet, New GM also admits to its customers that lightening the key chain may not help as "rough road conditions or other jarring impact related events" could cause the vehicle to experience full loss of power, steering, braking and air bag deployment. See Mar. 24, 2014 Letter from Senator Blumenthal to Attorney General Holder. Appropriately, the Old GM engineer who designed the ignition switch called it "the switch from hell." Report to the Board of Directors of General Motors Company Regarding the Ignition Switch Recalls, authored by Anton R. Valukas of Jenner & Block (May 29, 2014) (or "Valukas Report") at 5.

- 4. New GM's refusal to honestly speak about the defective ignition switch has gone on too long—more than four and a half years since Old GM filed for bankruptcy. Throughout that time, New GM knew of the life-threatening danger, and yet concealed the risk from drivers. Considering both the time that Old GM discovered the ignition switch defect and the time that New GM learned about it, thirteen years have passed. New GM belatedly admits that there has been a death for every year of their collective silence. But a recent report suggests that the death toll is exponentially higher than New GM admits, with the number actually in the hundreds. See March 13, 2014 Letter from Center for Auto Safety to the Honorable David J. Friedman ("On March 7, the Center for Auto Safety (CAS) wrote you about NHTSA's failure to utilize its Special Crash Investigations (SCI) of 2005 Cobalts and 2004 Ions and Early Warning Reports (EWR) of death claims filed by GM to open a defect investigation and order a recall. Examination of NHTSA's Fatal Analysis Reporting System (FARS) reveals 303 deaths of front seat occupants in the recalled 2005-07 Cobalts and 2003-07 Ions where the airbag failed to deploy in non-rear impact crashes."). This new figure is drawn from data on only two of the six recalled models, the Chevrolet Cobalt and Saturn Ion. The death toll is expected to increase significantly as the full gamut of defective vehicles and incidents come to light.
- 5. Old GM remained silent in 2001 when it received evidence that there was a problem with the now-recalled ignition switch in a pre-production Saturn Ion.
- 6. Old GM remained silent in 2004, when two Old GM engineers reported that the Ion's ignition switch could accidently turn off if inadvertently hit by the driver's knee. *See* March 11, 2014 Letter from GM to Nancy Lewis re: NHTSA Recall No. 14V-047; *see also* GM Recall Timeline. At that time, Old GM's engineers reportedly considered several remedies to increase torque in the key cylinder, but no action was taken "after consideration of the lead time

required, cost and effectiveness of each of these solutions." *See* March 11, 2014 Letter from GM to Ms. Nancy Lewis re: NHTSA Recall No. 14V-047. Old GM remained silent throughout 2005, when it received numerous reports of its customers' vehicles stalling, including a fatal crash in which a Cobalt's airbags did not deploy. A proposal to redesign the ignition key was approved by Old GM, then cancelled for undisclosed reasons. Old GM sent its dealers a bulletin instructing them to tell customers who complained of stalling to remove extra items from their key chains. Old GM also developed a key insert to prevent the key ring from hanging so low, but warranty records indicate that only 474 customers received one, compared to the more than one million vehicles sold.

- 7. Old GM remained silent in 2006, when more than 30 complaints had been filed with the National Highway Traffic Safety Administration ("NHTSA") about unexpected stopping and stalling—at least a dozen of these complaints involved the 2005 Chevrolet Cobalt.
- 8. Old GM remained silent in 2007, when it began tracking frontal-impact Cobalt crashes with no airbag deployment and discovered that in four of ten of such incidents the ignition was in "accessory" mode. Old GM also remained silent about the defects when it elected to discontinue the Ion that same year, and when over 80 complaints about unexpected stopping or stalling were filed with the NHTSA, including at least 30 involving the now-recalled 2005 Chevrolet Cobalt.
- 9. Old GM remained silent in 2008, when the NHTSA received 90 complaints about unexpected stopping or stalling for the now-recalled vehicles, including at least eight involving the 2006 Chevrolet HHR.
- 10. Old GM remained silent in 2009, as the NHTSA complaint toll reached 120, including at least one 2007 Chevrolet Cobalt.

- 11. New GM remained silent in 2009 when Old GM employees, officers, and managers with knowledge of the issue came to work for New GM.
- 12. New GM remained silent in 2009 when it acquired Old GM's books and records pursuant to the June 26, 2009 Amended and Restated Master Sale and Purchase Agreement and subsequent Sale Order, which referenced and detailed the defective ignition switch.
- 13. New GM remained silent in 2010, as the NHTSA complaint toll reached 170, including at least thirty-five involving the 2006 Chevrolet Cobalt.
- 14. New GM remained silent in 2013 when a technical expert discovered that the ignition switches in Ions and early-model Cobalts did not meet GM's torque specifications. Records reveal that Delphi Mechatronics provided Old GM with documents uncovering the 2006 ignition design change.
- 15. GM's silence over the past thirteen years speaks volumes. It resounds with an egregious and unprecedented failure to disclose a known defect, and reaches a crescendo of complete and utter disregard for human life. And, just "[a]s we must account for every idle word, so must we account for every idle silence." The time for silence is over.

III. PARTIES

- 16. The Named Plaintiffs are those individuals listed on the attached Exhibit A, which are incorporated herein as if set forth *in extenso*.
- 17. The Named Plaintiffs listed in Exhibit A assert claims against Defendant General Motors LLC for personal injury and/or wrongful death stemming from pre-sale accidents—that is, the accidents in question occurred before July 10, 2009.
- 18. The Named Plaintiffs' claims involve one or more of the following GM vehicles:

 (a) the First Wave Defective Vehicles, consisting of Chevrolet Cobalt (2005-2010 model years);

Chevrolet HHR (2006-2011 model years); Pontiac GS (2006-2007 model years); Pontiac Solstice (2006-2010 model years); Saturn Ions (2003-2007 model years); Saturn Sky (2007-2010 model years); and (b) the Second Wave Defective Vehicles, consisting of Buick LaCrosse (2005-2009 model years); Buick Lucerne (2006-2011 model years); Buick Regal LS (2004-2005 model years); Buick Regal GS (2004-2005 model years); Cadillac Deville (2000-2005 model years); Cadillac DTS (2004-2011 model years); Cadillac CTS (2003-2014 model years); Cadillac SRX (2004-2006 model years); Chevrolet Camaro (2010-2014 model years); Chevrolet Impala (2000-2014 model years); Chevrolet Monte Carlo (2000-2008 model years); Chevrolet Malibu (1997-2005 model years); Oldsmobile Intrigue (1998-2002 model years); Oldsmobile Alero (1999-2004 model years); Pontiac Grand Am (1999-2005 model years); Pontiac Grand Prix (2004-2008 model years); Daewoo G2x (2007-2009 model years); Opal GT (2007-2010 model years); Pontiac Pursuit (2005-2007 model years); and Vauxhall GT (2007-2010 model years). The First Waver Defective Vehicles and the Second Wave Defective Vehicles are collectively the "Defective Vehicles."

19. Defendant General Motors, LLC ("New GM"), is a Delaware limited liability company. On July 10, 2009, General Motors, LLC acquired substantially all of the assets and acquired certain liabilities of General Motors Corporation by way of a Section 363 sale under Chapter 11 of the Bankruptcy Code. New GM acquired specific liabilities of Old GM, who filed a voluntary petition for relief under Chapter 11 of the U.S. Bankruptcy Code on June 1, 2009. New GM acquired substantially all of Old GM's employees, officers and management personnel. New GM also acquired Old GM's designs, tools, inventory, books, records, and its key contracts, among other essential assets. The Named Plaintiffs' causes of action in this

¹ Benjamin Franklin.

lawsuit are brought against New GM, and Plaintiffs do not assert any causes of action against General Motors Corporation ("Old GM").

- 20. Under the June 26, 2009 Amended and Restated Master Sale and Purchase Agreement, New GM expressly acquired liability for post-sale accidents involving Old GM vehicles causing personal injury, loss of life or property damage.
- 21. New GM also expressly acquired certain liabilities of Old GM, including certain statutory requirements:

From and after the Closing, Purchaser [New GM] shall comply with the certification, reporting and recall requirements of the National Traffic and Motor Vehicle Safety Act, the Transportation Recall Enhancement, Accountability and Documentation Act, the Clean Air Act, the California Health and Safety Code and similar Laws, in each case, to the extent applicable in respect of vehicles and vehicle parts manufactured or distributed by Seller.

22. In addition, [New GM] expressly set forth that it:

shall be responsible for the administration, management and payment of all Liabilities arising under (i) express written warranties of Sellers [General Motors Corporation] that are specifically identified as warranties and delivered in connection with the sale of new, certified used or pre-owned vehicles or new or remanufactured motor vehicle parts and equipment (including service parts, accessories, engines and transmissions) manufactured or sold by Sellers or Purchaser prior to or after the Closing and (ii) Lemon Laws.

23. At all times relevant to the claims in this lawsuit, Old GM and New GM were in the business of developing, manufacturing, and marketing cars throughout the United States generally, and specifically in each of the states of citizenship identified in Exhibit A. New GM has a network of authorized retailers that sell its vehicles and parts throughout the United States. New GM maintains its principal place of business at 300 Renaissance Center, Detroit, Michigan.

IV. JURISDICTION AND VENUE

24. Plaintiffs' filing of this Complaint in this district does not alter the choice-of-law analysis and does not constitute a waiver of any of Plaintiffs' rights to transfer to another district

at the conclusion of pretrial proceedings in this case. Named Plaintiffs have filed this Complaint in this district in order to advance the efficient and orderly resolution of claims arising from Defendants' conduct and its attendant nationwide devastating effects. At the conclusion of pretrial proceedings in this case, each Named Plaintiff will be entitled to transfer of his or her claim to the state of his or her residence as listed on the attached Exhibit A.

25. This Court has diversity jurisdiction over this action under 28 U.S.C. § 1332(a) because the amount in controversy exceeds \$75,000.00 and Named Plaintiffs are citizens of different states than Defendant.

V. FACTUAL BACKGROUND

A. General Background

- 26. An auto manufacturer should never make profits more important than safety and should never conceal from consumers or the public any defects that exist in its vehicles. New GM's Vehicle Safety Chief, Jeff Boyer recently proclaimed that: "Nothing is more important than the safety of our customers in the vehicles they drive." *GM Announces New Vehicle Safety Chief*, http://democrats.energycommerce.house.gov/sites/default/files/documents/Testimony-Barra-GM-Ignition-Switch-Recall-2014-4-1.pdf Yet New GM failed to live up to this commitment. Appropriately, the Old GM engineer who designed the ignition switch called it "the switch from hell." *Report to the Board of Directors of General Motors Company Regarding the Ignition Switch Recalls*, authored by Anton R. Valukas of Jenner & Block (May 29, 2014) (or "Valukas Report") at 5.
- 27. The first priority of a car manufacturer should be to ensure that its vehicles are safe, and particularly that its vehicles have operable ignition systems, airbags, power-steering, power brakes, and other safety features that can prevent or minimize the threat of death or

serious bodily harm in a collision. In addition, a car manufacturer must take all reasonable steps to ensure that, once a vehicle is running, it operates safely, and its critical safety systems (such as engine control, braking, and airbag systems) work properly until such time as the driver shuts down the vehicle. Moreover, a manufacturer that is aware of dangerous design defects that cause its vehicles to shut down during operation, or its airbags not to deploy, must promptly disclose and remedy such defects.

28. To date, GM has sold at least 15 million automobiles installed with defective ignition switches which slip into the "accessory" or "off" position and turn off the engine and the car's vital engine systems without warning while the car is in motion. This ignition switch defect disables the power steering and power brakes and prevents the deployment of air bags in the vehicles.

B. GM's Knowledge of Safety-Related Defects and Its Concealment of those Defects

29. It has now come to light that the GM vehicles had safety related design defects that were known by Old GM as early as 2001, and by New GM as a result of the acquired knowledge from employees, officers, and managers and the books and records that New GM obtained and/or acquired as a result of the 2009 sale. During pre-production development of the Ion in 2001, Old GM became aware of issues relating to its ignition switch "passlock" system. Old GM's 2001 internal report stated the problem included a "low detent plunger force" in the ignition switch. In 2003, before the launch of the 2005 Cobalt, Old GM became aware of incidents wherein the vehicle engine would suddenly lose power in the event the key moved out of the "run" position when the driver inadvertently contacted the key or steering column. An investigation of these issues was opened and, after consideration of the lead-time required and the cost effectiveness of potential solutions, the investigation was closed with no

action taken.

- 30. The design of the ignition switch, position of the key lock module, and slot design of the key are hereinafter referred to as the "Key System."
- 31. In 2002, Old GM began manufacturing and selling 2003 Saturn Ions with the defective Key System. It later began selling Chevrolet Cobalts with the same defective Key System.
- 32. In 2004, Old GM engineers reported that the ignition switch on the Saturn Ion was so weak and so low on the steering column that a driver's knee could easily bump the key and turn off the vehicle. This defect was sufficiently serious for an Old GM engineer, in January 2004, as part of Old GM's vehicle evaluation program, to affirmatively conclude, in writing, that "[t]his is a basic design flaw and should be corrected if we want repeat sales."
- 33. In 2004, Old GM began manufacturing and selling the 2005 Chevrolet Cobalt. The Cobalt was a sister vehicle (essentially the same car with a different badge or name) of the Saturn Ion. As noted, Old GM installed the same Key System on the 2005 Cobalt as it did on the Saturn Ion.
- 34. On October 29, 2004, around the time of Old GM's market launch of the 2005 Cobalt, Gary Altman Old GM's program-engineering manager for the Cobalt test-drove the Cobalt with the standard key and key fob. During the test drive, when Altman's knee bumped the key, the engine turned off, causing the engine to stall. Altman reported this incident to GM.
- 35. In response to Altman's report, Old GM launched an engineering inquiry to investigate the potential for the key to move from the "run" to the "accessory/off" position during ordinary driving conditions. This inquiry is known within GM as a Problem Resolution

Tracking System Inquiry ("PRTS"). The specific complaint which resulted in the PRTS was that the "the vehicle can be keyed off with knee while driving."

36. On February 1, 2005, as part of the PRTS, Old GM engineers concluded:

There are two main reasons that [sic] we believe can cause a lower effort in turning the key: 1. A low torque detent in the ignition switch. 2. A low position of the lock module in the column. (PRTS — Complete Report N172404).

As part of the PRTS, Old GM engineers also began looking into ways to solve the problem of the key moving from the "run" to the "accessory/off" position during ordinary driving.

- 37. On February 18, 2005, Old GM engineers presented several possible solutions to the Cockpit Program Integration Team ("CPIT"). Old GM engineers determined the only "sure solution" to resolve the problem of the key inadvertently moving from the "run" to the "accessory/off" position required changing from a low mount to a high mount lock module, which would considerably reduce the possibility of the key/key fob being impacted by a driver. According to Old GM engineers, this change in the key position on the lock module, combined with increasing the detent in the ignition switch, would be a "sure solution." Old GM, however, through Altman, rejected this "sure solution," in part, because the cost to implement the solution would be too high.
- 38. During this PRTS, Old GM also considered changing the key from a slot to a hole as a way to attempt to contain this problem, but not as a solution to the problem. Changing the key from a slot to a hole would reduce the lever arm of the key and the key chain. With the slot design, the key chain would hang lower on the key which would increase the torque force on the ignition switch when the chain was contacted or moved in any way. Old GM engineers determined this key change would significantly reduce the chance of the key inadvertently moving from the "run" to the "accessory/off" position during ordinary driving maneuvers.

39. An Old GM engineer conducted a cost analysis of this key change and determined that the cost to make this change would be less than one dollar per vehicle or around 57 cents per part. Old GM, however, rejected this proposed key change and, on March 9, 2005, Old GM closed the PRTS without taking any steps to fix the defective Key System in Ions and Cobalts. The PRTS detailed the reasons why Old GM took no action.

Per GMX001 PEM's [Gary Altrnan] directive we are closing this PRTS with no action. The main reasons are as follows: All possible solutions were presented to CPIT and VAPTR: a. The lead-time for all the solutions is too long. b. The tooling cost and piece price are too high. c. None of the solutions seem to fully countermeasure the possibility of the key being turned (ignition turn off) during driving. Thus **none of the solutions represents an acceptable business case** (emphasis added).

40. On February 28, 2005, Old GM issued a bulletin to its dealers regarding engine-stalling incidents in 2005 Cobalts and 2005 Pontiac Pursuits (the Canadian version of the Pontiac G5). The February 28, 2005 bulletin addressed the potential for drivers of these vehicles to inadvertently turn off the ignition due to low key ignition cylinder torque/effort. In the February 28, 2005 bulletin, Old GM provided the following recommendations/instructions to its dealers — but not to the Named Plaintiffs or to the public in general:

There is potential for the driver to inadvertently turn off the ignition due to low key ignition cylinder torque/effort. The concern is more likely to occur if the driver is short and has a large heavy key chain.

In the cases this condition was documented, the driver's knee would contact the key chain while the vehicle was turning. The steering column was adjusted all the way down. This is more likely to happen to a person that is short as they will have the seat positioned closer to the steering column.

In cases that fit this profile, question the customer thoroughly to determine if this may be the cause. The customer should be advised of this potential and to take steps, such as removing unessential items from their key chains, to prevent it.

Please follow this diagnosis process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

- 41. At that time, however, Old GM knew that the inadvertent turning off of the ignition in the vehicles was due to design defects in the Key System in those vehicles, including the Saturn Ion, and was not limited to short drivers using large heavy key chains. Simply stated, as of February 2005, Old GM engineers knew that the Saturn Ion and Chevrolet Cobalt vehicles had the Key System safety-related defects discussed in this Complaint. GM failed to disclose and, in fact, concealed, the February 28, 2005 bulletin and/or the information contained therein, from Saturn Ion and Chevrolet Cobalt owners, including the Named Plaintiffs, and sent affirmative representations to dealers that did not accurately describe the nature of the problem, the multiple design steps needed for a "sure solution" to the problem, and GM's knowledge of it.
- 42. Indeed, rather than disclosing this serious safety problem that uniformly affected all Saturn Ion cars, GM, instead, concealed and obscured the problems, electing to wait until customers brought their cars to a dealership after an engine-stalling incident, and offered even its own dealers only an incomplete, incorrect, and insufficient description of the defects and the steps necessary to actually remedy them.
- 43. Under 49 C.F.R. § 573.6, GM was required to "furnish a report to the NHTSA for each defect . . . related to motor vehicle safety." Instead of complying with its legal obligations, GM fraudulently concealed the Key System defect from the public including Named Plaintiffs and continued to manufacture and sell Ions and Cobalts with these known safety defects, causing the Named Plaintiffs to continue to own, operate or ride in vehicles that contained defective and dangerous ignition switches.

44. In March 2005, following its receipt of a customer complaint that his/her Cobalt vehicle ignition turned off while driving, Old GM opened another PRTS — Complete Report (0793/2005-US). Steve Oakley, the brand quality manager for the Cobalt, originated the PRTS. As part of the PRTS, Mr. Oakley reviewed an email dated March 9, 2005 from Jack Weber, an Old GM engineer. The subject of the email was "Cobalt SS Ignition Turn Off." In the email, Mr. Weber stated:

I've had a chance to drive a Cobalt SS and attempt to turn off the ignition during heel/toe down shifting. Much to my surprise, the first time I turned off the ignition switch was during a normal traffic brake application on I96. After that I was able to do a static reproduction of the condition in a parking lot. I've attached photos of the condition with comments. My Anthropometric

Measurements are attached below:

Static view of keys, fob and registration hitting knee.

Position of RKE fob during normal driving. Dynamic evaluation. View of steering column cover and Pass Key 3+ "lump" under the key slot.

Key in run position, knee contacting the fob and the split ring is pulling on the key to move it to the "off" position. Static evaluation. Fob has levered around the steering column cover and turned the ignition off.

Unobstructed view of the fob and column cover.

Attached below is documentation of a RAMSIS study performed to attempt to duplicate the real world condition.

Please call at (586) 986-0622 with questions.

Jack Weber

Mr. Weber clearly identified the defects in the Key System while he was driving the Cobalt, which is essentially the same vehicle as the Saturn Ion.

45. Despite the clear evidence of the safety-related defect with the Key System, during the March 2005 PRTS, Old GM engineers decided not to reconsider any of the proposed solutions discussed during the February 2005 PRTS. Instead, the Old GM engineers leading the PRTS recommended that the sole corrective action GM should recommend would be to advise

customers to remove excess material from their key rings. This recommendation was made despite the fact that Old GM knew that the inadvertent turning off of the ignition in these vehicles was due to design defects in the Key System, and was not limited to drivers having excess key ring materials.

- 46. In May 2005, Old GM, following its receipt of another customer complaint that the customer's Cobalt ignition turned off while driving, opened another PRTS. During the May 2005 PRTS, Old GM decided to redesign the key in order to reduce the possibility that a driver may inadvertently turn the key from the "run" to the "accessory/off" position during ordinary driving.
- 47. Despite this initial safety/redesign commitment, however, Old GM ultimately failed to follow through on its own decision and closed this PRTS without any action, further concealing what it knew from the public and continuing to subject the public, including the Named Plaintiffs, to the Defective Vehicles' serious safety risks.
- 48. At or about this same time, Old GM, through Alan Adler, Old GM's Manager, Product Safety Communications, issued the following statement with respect to the Chevrolet Cobalt's inadvertent shut-off problems, affirmatively representing in its "Statement on Chevrolet Cobalt Inadvertent Shut-offs" that:

In rare cases when a combination of factors is present, a Chevrolet Cobalt driver can cut power to the engine by inadvertently bumping the ignition key to the accessory or off position while the car is running.

When this happens, the Cobalt is still controllable. The engine can be restarted after shifting to neutral.

GM has analyzed this condition and believes it may occur when a driver overloads a key ring, or when the driver's leg moves amid factors such as steering column position, seat height and placement.

Depending on these factors, a driver can unintentionally turn the vehicle off.

Service advisers are telling customers they can virtually eliminate this possibility by taking several steps, including removing non-essential material from their key rings.

Ignition systems are designed to have "on" and "off' positions, and practically any vehicle can have power to a running engine cut off by inadvertently bumping the ignition from the run to accessory or off position.

- 49. Old GM's statement, however, was demonstrably false and misleading. Old GM's internal testing documents showed that these incidents occurred when drivers were using keys with the standard key fob. GM knew that these incidents were not caused by heavy key chains or a driver's size and seating position. GM also knew that removing the non-essential material from key rings would not "virtually eliminate" the possibility of inadvertent bumping of the ignition key from the "run" to the "accessory/off" position while the car was running.
- 50. GM's above-referenced statement was further demonstrably false and misleading because GM knew that these incidents were ultimately caused by the safety-related defects in the Key System identified in the February 2005 PRTS. GM's affirmative concealment of the problems with the defective vehicles, including the Saturn Ion and Cobalt cars, did not end there.
- 51. On July 29 2005, Amber Marie Rose ("Amber"), a sixteen-year-old Clinton, Maryland resident, was driving a 2005 Cobalt when she drove off the road and struck a tree head-on. Amber's driver's side frontal airbag did not deploy and she died as a result of the injuries she sustained in the crash.
- 52. Old GM received notice of Amber's incident in September 2005 and shortly thereafter opened an internal investigation file concerning the incident. During its investigation of the incident, Old GM learned that the key in Amber's Cobalt was in the "accessory/off"

position at the time of the crash. During its investigation, Old GM also knew that the driver's side frontal airbag should have deployed given the circumstances of Amber's crash. Upon information and belief, Old GM subsequently entered into a confidential settlement agreement with Amber's mother.

53. In December 2005, shortly after it commenced its internal investigation into the incident leading to Amber's death, Old GM issued a Technical Service Bulletin (05-02-35-007) (the "TSB"). The TSB, which GM affirmatively represented applied to 2005-2006 Chevrolet Cobalts, 2006 Chevrolet 1-11-1Rs, 2005-2006 Pontiac Pursuit, 2006 Pontiac Solstices, and 2003-2006 Saturn Ions, provided, "Information on inadvertent Turning of Key Cylinder, Loss of Electrical System and no DTCs," provided the following service information:

There is potential for the driver to inadvertently turn off the ignition due to low ignition key cylinder torque/effort.

The concern is more likely to occur if the driver is short and has a large and/or heavy key chain. In these cases, this condition was documented and the driver's knee would contact the key chain while the vehicle was turning and the steering column was adjusted all the way down. This is more likely to happen to a person who is short, as they have the seat positioned closer to the steering column.

In cases that fit this profile, question the customer thoroughly to determine if this may be the cause. The customer should be advised of this potential and should take steps to prevent it - such as removing unessential items from their key chain.

Engineering has come up with an insert for the key ring so that it goes from a "slot" design to a hole design. As a result, the key ring cannot move up and down in the slot any longer - it can only rotate on the hole. In addition, the previous key ring has been replaced with a smaller, 13 mm (0.5 in) design. This will result in the keys not hanging as low as in the past.

54. As with its prior statements regarding the Defective Vehicles, the information Old GM provided in this TSB was also false and misleading. In the two PRTSs GM issued before it

issued the TSB, GM engineers never represented that short drivers or heavy key chains were the reasons why these incidents were happening. Indeed, at the time it issued the TSB, Old GM knew that these incidents were happening to drivers of all sizes using keys with the standard key fobs. In other words, Old GM knew these incidents were not caused by short drivers with heavy key chains, but were caused by the safety-related defects in the Key System of its Defective Vehicles, including the Chevrolet Cobalt.

- 55. Not only did GM fail to address the safety defects, it covered-up and fraudulently concealed the facts from the Named Plaintiffs and the driving public. One GM Quality Service Manager, who drafted a TSB in connection with the ignition switch defects, stated "the term 'stall' is a 'hot' word that GM generally does not use in bulletins because it may raise a concern about vehicle safety, which suggests GM should recall the vehicle, not issue a bulletin." Valukas Report at 92. GM personnel stated that "there was concern about the use of 'stall' in a TSB because such language might draw the attention of NHTSA." *Id.* at 93.
- 56. GM's widespread cover-up and deception was brought to light in the Valukas Report. Multiple GM employees confirmed that GM intentionally avoids using the word "stall" "because such language might draw the attention of NHTSA" and "may raise a concern about safety, which suggests GM should recall the vehicle" Even GM's CEO, Mary Barra, testified on June 18, 2014, before the United States House of Representatives Committee on Energy and Commerce, Subcommittee on Oversight and Investigation, that "we consider a stall to be a safety issue."
- 57. In 2005, Old GM began buying back Cobalts from certain customers who were experiencing engine stalling incidents. GM never told the public, including the Named Plaintiffs, that it was buying back Cobalts under these circumstances. GM refused to buy back Cobalts

from other customers who had also experienced engine-stalling incidents. In fact, for many of the customers who complained about experiencing engine-stalling incidents, GM never informed these customers of the TSB and/or the availability of the key insert.

- 58. On November 17, 2005, shortly after Amber's death and immediately before Old GM's issuance of the TSB, there was another incident involving a 2005 Cobalt in Baldwin, Louisiana. In that incident, the Cobalt went off the road and hit a tree. The frontal airbags did not deploy. Old GM received notice of this accident, opened a file, and referred to it as the "Colbert" incident.
- 59. On February 10, 2006, in Lanexa, Virginia, shortly after Old GM issued the TSB, a 2005 Cobalt drove off of the road and hit a light pole. As with the Colbert incident (above), the frontal airbags failed to deploy. The download of the SDM (the vehicle's "black box") showed the key was in the "accessory/off" position at the time of the crash. Old GM received notice of this accident, opened a file, and referred to it as the "Carroll" incident.
- 60. On March 14, 2006, in Frederick, Maryland, a 2005 Cobalt traveled off the road and struck a utility pole. The frontal airbags did not deploy. The download of the SDM showed the key was in the "accessory/off" position at the time of the crash. Old GM received notice of this incident, opened a file, and referred to it as the "Oakley" incident.
- 61. On August 1, 2006, following its receipt of a customer complaint about a Cobalt stalling while driving, Old GM opened yet another PRTS relating to this issue. Old GM closed this PRTS on October 2, 2006 without taking any action.
- 62. In October 2006, Old GM updated the TSB (05-02-35-007) to include additional model years: the 2007 Saturn Ion and Sky, 2007 Chevrolet HEIR, 2007 Cobalt and 2007 Pontiac

Solstice and Pontiac 05 vehicles. These vehicles had the same safety-related defects in the Key System as the vehicles in the original TSB.

- 63. On December 29, 2006, in Sellenville, Pennsylvania, a 2005 Cobalt drove off the road and hit a tree. The frontal airbags failed to deploy. Old GM received notice of this incident, opened a file, and referred to it as the "Frei" incident.
- 64. On February 6, 2007, in Shaker Township, Pennsylvania, a 2006 Cobalt sailed off the road and struck a truck. Despite there being a frontal impact in this incident, the frontal airbags failed to deploy. The download of the SDM showed the key was in the "accessory/off" position. Old GM received notice of this incident, opened a file, and referred to it as the "White" incident.
- 65. On August 6, 2007, in Cross Lanes, West Virginia, a 2006 Cobalt rear-ended a truck. The frontal airbags failed to deploy. Old GM received notice of this incident, opened a file, and referred to it as the "McCormick" incident.
- 66. On September 25, 2007, in New Orleans, Louisiana, a 2007 Chevrolet Cobalt lost control and struck a guardrail. Despite there being a frontal impact in this incident, the frontal airbags failed to deploy. Old GM received notice of this incident, opened a file, and referred to it as the "Gathe" incident.
- 67. On October 16 2007, in Lyndhurst, Ohio, a 2005 Chevrolet Cobalt traveled off road and hit a tree. The frontal airbags failed to deploy. Old GM received notice of this incident, opened a file, and referred to it as the "Breen" incident.
- 68. On April 5, 2008, in Sommerville, Tennessee, a 2006 Chevrolet Cobalt traveled off the road and struck a tree. Despite there being a frontal impact in this incident, the frontal airbags failed to deploy. The download of the SDM showed the key was in the "accessory/off"

position. Old GM received notice of this incident, opened a file, and referred to it as the "Freeman" incident.

- 69. On May 21, 2008, in Argyle, Wisconsin, a 2007 Pontiac G5 traveled off the road and struck a tree. Despite there being a frontal impact in this incident, the frontal airbags failed to deploy. The download of the SDM showed the key was in the "accessory/off" position. Old GM received notice of this incident, opened a file, and referred to it as the "Wild" incident.
- 70. On May 28, 2008, in Lufkin, Texas, a 2007 Chevrolet Cobalt traveled off the road and struck a tree. Despite there being a frontal impact in this incident, the frontal airbags failed to deploy. Old GM received notice of this incident, opened a file, and referred to it as the "McDonald" incident.
- 71. On September 13, 2008, in Lincoln Township, Michigan, a 2006 Chevrolet Cobalt traveled off the road and struck a tree. Despite there being a frontal impact in this incident, the frontal airbags failed to deploy. Old GM received notice of this incident, opened a file, and referred to it as the "Harding" incident.
- 72. In 2008, in Rolling Hills Estates, California, a 2008 Chevrolet Cobalt traveled off the road and hit a tree. Despite there being a frontal impact in this incident, the frontal airbags failed to deploy. Old GM received notice of this incident, opened a file, and referred to it as the "Dunn" incident.
- 73. On December 6, 2008, in Lake Placid, Florida, a 2007 Chevrolet Cobalt traveled off the road and hit a utility pole. Despite there being a frontal impact in this incident, the frontal airbags failed to deploy. The download of the SDM showed the key was in the "accessory/off" position. Old GM received notice of this incident, opened a file, and referred to it as the "Grondona" incident.

- 74. In February 2009, Old GM opened yet another PRTS with respect to the Defective Vehicles this time to investigate why the slot in the key in Cobalts allowed the key chain to hang too low in the vehicles, as well as the inadvertent shutting off of the vehicles. Through this PRTS, Old GM determined that changing the key from a slot to a hole would significantly reduce the likelihood of the ignition switch inadvertently turning off.
- 75. In March 2009, Old GM approved of the design change in the key from the slot to a hole. According to GM, this redesigned change was implemented in model year 2010 Chevrolet Cobalts. GM, however, chose not to provide these redesigned keys to the owners or lessees of any of the vehicles implicated in the TSB, including the 2005 Cobalt
- 76. The following timeline gives a short overview of some key points between 2004 and the present, as discussed above:

	2005-2009	
	GM learns of	2010-2014
	hundreds of field	GM learns of more
2001-2004	reports of Key	field reports of
GM learns	System failures	Key System
Key Systems	and multiple	failures and
are defective.	fatalities.	additional fatalities.

2005	2009	2014
GM engineers'	GM declares and	GM issues inadequate
proposed fix	emerges from	recall over 10 years
rejected; Amber	bankruptcy	after learning its
Rose dies after		Key Systems are
airbag in Cobalt		defective
fails to deploy		

77. Throughout this time period, GM was selling the Defective Vehicles to consumers for full price, and consumers were purchasing them believing that the vehicles were non-defective, but all the while GM was concealing the extent and nature of the defects in the Defective Vehicles.

C. Old GM's Marketing Represented to the Public that the Defective Vehicles Were Safe.

78. In a section called "safety," Old GM's Chevrolet website stated:

OUR COMMITMENT

Your family's safety is important to us. Whether it's a short errand around town or a cross-country road trip, Chevrolet is committed to keeping you and your family safe — from the start of your journey to your destination. That's why every Chevrolet is designed with a comprehensive list of safety and security features to help give you peace of mind. Choose from the safety features below to learn more about how they work, and which Chevy vehicles offer them.

79. Similarly, Old GM promoted its Saturn vehicle line on television with statements like "Putting people first," and "Saturn. People First." Saturn's print ad campaign featured advertisements like the following, which stated, among other things: "Need is where you begin. In cars, it's about things like reliability, durability and, of course, safety. That's where we started when developing our new line of cars." In sum, in order to increase sales, Old GM touted the safety of its vehicles. But, when the time came for the company to stay true to its words, GM did not disclose its knowledge about the dangerous Key System defects to its customers, including the Named Plaintiffs.

D. Meet the New GM, Same as the Old GM

- 80. In 2009, GM declared bankruptcy and, weeks later, it emerged from bankruptcy. Both before and after GM's bankruptcy, the Key Systems in the Defective Vehicles continued to fail and New GM, in all iterations, continued to conceal the truth.
- 81. On May 15, 2009, New GM again met with Continental AG, an airbag component supplier, and requested that Continental download SDM data from a 2006 Chevrolet Cobalt accident where the airbags failed to deploy.

- 82. On December 31, 2010, in Rutherford County, Tennessee, a 2006 Chevrolet Cobalt traveled off the road and struck a tree. Despite there being a frontal impact in this incident, the frontal airbags failed to deploy. The download of the SDM showed the key was in the "accessory/off' position. New GM received notice of this incident, opened a file, and referred to it as the "Chansuthus" incident.
- 83. On December 31, 2010, in Harlingen, Texas, a 2006 Chevrolet Cobalt traveled off the road and struck a curb. Despite there being a frontal impact in this incident, the frontal airbags failed to deploy. New GM received notice of this incident, opened a file, and referred to it as the "Najera" incident.
- 84. On March 22, 2011, Ryan Jahr, a New GM engineer, downloaded the SDM from a Cobalt. The information from the SDM download showed that the key in that Cobalt turned from the "run" to the "accessory/off" position 3 to 4 seconds before the crash.
- 85. On December 18, 2011, in Parksville, South Carolina, a 2007 Chevrolet Cobalt traveled off the road and struck a tree. Despite there being a frontal impact in this incident, the frontal airbags failed to deploy. The download of the SDM showed the key was in the "accessory/off" position. New GM received notice of this incident, opened a file, and referred to it as the "Sullivan" incident.
- 86. These incidents are not limited to vehicles of model year 2007 and before. According to New GM's own investigation, there have been over 250 crashes involving 2008-2010 GM vehicles in which the airbags failed to deploy.
- 87. In 2010, New GM began a formal investigation of the frontal airbag non-deployment incidents in Chevrolet Cobalts and Pontiac G5s. GM subsequently elevated the investigation to a Field Performance Evaluation ("FPE").

- 88. In August 2011, New GM assigned Engineering Group Manager, Brian Stouffer as the Field Performance Assessment Engineer ("FPAE") to assist with the FPE investigation.
- 89. In Spring 2012, Stouffer asked Jim Federico, a high-level executive and chief engineer at New GM, to oversee the FPE investigation. Federico was the "executive champion" for the investigation to help coordinate resources for the FPE investigation.
- 90. In May 2012, New GM engineers tested the torque on the ignition switches for 2005-2009 Cobalts, 2007 and 2009 Pontiac 05s, 2006-2009 HHRs, and 2003-2007 Saturn Ion vehicles in a junkyard. The results of these tests showed that the torque required to turn the ignition switches in most of these vehicles from the "run" to the "accessory/off" position did not meet GM's minimum torque specification requirements. These results were reported to Stouffer and other members of the FPE.
- 91. In September 2012, Stouffer requested assistance from a "Red X Team" as part of the FPE investigation. The Red X Team was a group of engineers within New GM assigned to find the root cause of the airbag non-deployments in frontal accidents involving GM vehicles. By that time, however, it was clear that the root cause of the airbag non-deployments in a majority of the frontal accidents was the defective Key System. The Red X Team became involved in the investigation shortly after Mr. Stouffer's request.
- 92. During the field-performance-evaluation process, New GM determined that, although increasing the detent in the ignition switch would reduce the chance that the key would inadvertently move from the "run" to the "accessory/off" position, it would not be a total solution to the problem. Indeed, the New GM engineers identified several additional ways to actually fix the problem. These ideas included adding a shroud to prevent a driver's knee from contacting the key, modifying the key and lock cylinder to orient the key in an upward facing

orientation when in the run position, and adding a push button to the lock cylinder to prevent it from slipping out of run. New GM rejected each of these ideas. New GM engineers understood that the key fob may be impacted and pinched between the driver's knee and the steering column which causes the key to be inadvertently turned from the run to accessory/off position. New GM engineers understood that increasing the detent in the ignition switch would not be a total solution to the problem. New GM engineers also believed that the additional changes to the Key System (such as the shroud) were necessary to fix the defects with the Key System. The New GM engineers clearly understood that increasing the detent in the ignition switch alone was not a solution to the problem but New GM concealed — and continued to conceal — from the public the nature and extent of the defects.

- 93. By 2012, Federico, Stouffer, and the remaining members of the Red X Team knew that the Key System in the Saturn Ion, the Cobalt, and the G5 vehicles had safety-related defects that would cause the key to move from the "run" to the "accessory/off" position while driving these vehicles. They also knew that when this happened the airbags would no longer work in frontal crashes. Federico, Stouffer, and the other members of the Red X Team also understood that these safety-related defects had caused or contributed to numerous accidents and multiple fatalities. Despite this knowledge, New GM chose to conceal this information from the public, NHTSA, and the Named Plaintiffs.
- 94. In December 2012, in Pensacola, Florida, Ebram Handy, a New GM engineer, participated in an inspection of components from Brooke Melton's Cobalt, including the ignition switch. At that inspection, Handy, along with Mark Hood, a mechanical engineer retained by the Meltons, conducted testing on the ignition switch from Brooke Melton's vehicle, as well as a replacement ignition-switch for the 2005 Cobalt.

95. At that inspection, Handy observed that the results of the testing showed that the torque performance on the ignition switch from Brooke Melton's Cobalt was well below GM's minimum torque performance specifications. Handy also observed that the torque performance on the replacement ignition switch was significantly higher than the torque performance on the ignition switch in Brooke Melton's Cobalt.

96. In January 2013, Handy, in preparation for a Rule 30(b)(6) deposition, spoke with several GM engineers, including DeGiorgio and Stouffer. At that time, Handy knew that, based on the testing he had observed, the original ignition switch in the 2005 Cobalt failed to meet GM's minimum torque performance specifications. New GM knew that an ignition switch that did not meet its minimum torque performance requirements was a safety-related defect.

E. GM Recalls

- 97. On February 7, 2014, New GM, in a letter from Carmen Benavides, Director of Product Investigations and Safety Regulations for New GM, notified the NHTSA that it was conducting Recall No. 13454 for certain 2005-2007 model year Chevrolet Cobalts and 2007 model year Pontiac 05 vehicles. In its February 7, 2014, letter to NHTSA, New GM represented that as replacement ignition switches became available, GM would replace the ignition switches on the Defective Vehicles.
- 98. On February 19, 2014, a request for timeliness query of General Motors' Safety Recall 13454 was sent to the NHTSA. The timeliness query pointed out that GM had failed to recall all of the vehicles with the defective ignition switches. The February 19, 2014 request for timeliness query also asked the NHTSA to investigate GM's failure to fulfill its legal obligation to report the safety-related defects in the Defective Vehicles to the NHTSA within five days of discovering the defect.

99. On February 24, 2014, New GM in a letter from Carmen Benavides, informed the NHTSA it was expanding the recall to include 2006-2007 model year (MY) Chevrolet I-EHR and Pontiac Solstice, 2003-2007 MY Saturn Ion, and 2007 MY Saturn Sky vehicles. GM included an Attachment to the February 24, 2014 letter. In the Attachment, New GM, **for the first time**, admitted that GM previously authorized a change in the ignition switch. Specifically, New GM stated:

On April 26, 2006, the GM design engineer responsible for the Cobalt's ignition switch signed a document approving changes to the ignition switch proposed by the supplier, Delphi Mechatronics. The approved changes included, among other things, the use of a new detent plunger and spring that increased torque force in the ignition switch. This change to the ignition switch was not reflected in a corresponding change in the part number for the ignition switch. GM believes that the supplier began providing the re-designed ignition switch to GM at some point during the 2007 model year. (GM's February 24, 2014 letter).

100. New GM then produced documents in response to Congressional requests leading up to the hearings on April 1 and 2, 2014. Among the documents produced by New GM is a document titled, "GENERAL MOTORS COMMODITY VALIDATION SIGN-OFF," dated April 26, 2006. According to this document, Delphi had met all of the sign-off requirements in order to provide a new ignition switch for certain GM vehicles. New GM has acknowledged that the ignition switch in the Cobalt was included in this design change. The design change included a new detent plunger "to increase torque force in the switch." DeGiorgio's signature is on this page as the GM authorized engineer who signed off on this change to the ignition switch. This GM Commodity Validation Sign-Off shows that DeGiorgio repeatedly perjured himself during his deposition on April 29, 2013. DeGiorgio perjured himself in order to fraudulently conceal evidence from the Plaintiffs that GM had signed off on the change in the ignition switch so that the Plaintiffs, and ultimately a jury, would never know that GM was changing the switches in

2007 and later model year Cobalts and concealing these changes. DeGiorgio perjured himself when he signed the errata sheet confirming that all the testimony was true and accurate.

F. The Named Plaintiffs' Specific Experiences.

101. The Named Plaintiffs incorporate each and every paragraph above as if fully set forth herein. Each of the Named Plaintiffs listed in Exhibit A assert a loss of vehicular control arising from an ignition switch defect of a GM vehicle resulting in the death and/or serious personal injuries of the Plaintiffs listed in Exhibit A.

VI. CLAIMS AGAINST GENERAL MOTORS, LLC BROUGHT BY ALL PLAINTIFFS LISTED IN EXHIBIT A

COUNT I – Negligence, Gross Negligence, Recklessness

- 102. The Named Plaintiffs re-allege as if fully set forth, each and every allegation set forth herein.
- Agreement wherein New GM acquired certain Old GM assets, New GM acquired knowledge of Old GM's activities and the defective ignition switch via the minds of the employees, officers and managers it acquired through the sale order. New GM acquired knowledge of Old GM's activities and the defective ignition switch via the books and records obtained and/or acquired as a result of the sale order. Thus, the duties of Old GM are part of the foundation for New GM's liability. Additionally, New GM's liability for damages is attributable to its own post-sale conduct.
- 104. Old GM and New GM owed Named Plaintiffs a duty to design, manufacture, fabricate, assemble, inspect, market, distribute, sell, and/or supply products in such a way as to avoid harm to persons using them such as Named Plaintiffs.

- 105. Old GM and New GM owed the Named Plaintiffs a duty to detect known safety defects in GM vehicles.
- 106. Old GM and New GM owed the Named Plaintiffs a duty, once it discovered the ignition switch defect, to provide thorough notice of the defect, including a warning that the defective vehicles should not be driven until an appropriate repair procedure is developed and performed.
- 107. Old GM and New GM owed the Named Plaintiffs a duty, once it discovered the ignition switch defect, to ensure that an appropriate repair procedure was developed and made available to drivers.
- 108. Old GM and New GM knew that their customers, such as the Named Plaintiffs, expect that the company will employ all reasonable efforts to detect safety defects, warn drivers of their existence, and develop and make available an appropriate repair procedure.
- 109. Old GM and New GM's efforts to discover, provide notice of, and provide repair procedures for safety related defects exist for the benefit of the Named Plaintiffs and other drivers of GM vehicles. Old GM and New GM was aware that by providing maintenance and repair information and assistance, including through its authorized dealerships, Old GM and New GM had a responsibility to the Named Plaintiffs and other drivers to take the reasonable measures listed above.
- 110. Independent of any failures by Old GM as described herein, between July 10, 2009 and March 2014, New GM breached its duties to the Named Plaintiffs by failing to provide appropriate notice of and repair procedures for the ignition switch defect in the Named Plaintiffs' vehicles. In doing so, New GM departed from the reasonable standard of care required of it.

- 111. It was foreseeable that if the New GM did not provide appropriate notice and repair procedures for the defect, the Named Plaintiffs and other drivers would be endangered.
- 112. The Named Plaintiffs' injuries were reasonably foreseeable to Old GM and New GM.
- 113. The Named Plaintiffs could not through the exercise of reasonable diligence have prevented the injuries caused by Old GM and New GM's negligence and gross negligence.
- 114. Old GM and New GM's acts and omissions, when viewed objectively from the actor's standpoint, involved an extreme degree of risk, considering the probability and magnitude of the potential harm to others. Old GM and New GM nevertheless proceeded with conscious indifference to the rights, safety and welfare of others.

COUNT II - Fraud by Non Disclosure

- 115. The Named Plaintiffs re-allege as if fully set forth, each and every allegation set forth herein.
- 116. As early as 2001, during pre-production development of the Saturn Ion, Old GM became aware of issues relating to the ignition switch "passlock" system. The 2001 report stated that the problem included a "low detent plunger force" in the ignition switch.
- 117. In 2003, before the launch of the 2005 Cobalt, Old GM became aware of incidents wherein the vehicle engine would suddenly lose power in the event the key moved out of the "run" position when the driver inadvertently contacted the key or steering column. An investigation was opened and, after consideration of lead-time required and the cost and effectiveness of potential solutions, the investigation was closed with no action taken.
- 118. As set forth above, from July 2009 to the present, New GM intentionally concealed or failed to disclose material facts from the Plaintiff, the public, and NHTSA

- 119. Additionally, from its inception in 2009, New GM possessed independent knowledge of the defects in the Named Plaintiffs' vehicles and the need to undertake multiple design steps to resolve those defects to prevent injury and economic harm to vehicle owners such as Plaintiffs. This knowledge was based, in part, on the information from records, files, reports and other documents and materials regarding the defective ignition switch maintained by Old GM, all of which were included in the assets purchased by New GM during the bankruptcy sale.
- land 120. Old GM had a duty to disclose the facts to the Named Plaintiffs and Old GM knew: (1) that the Named Plaintiffs were ignorant of the material facts that New GM did not disclose and/or intentionally concealed; and (2) the Named Plaintiffs did not have an equal opportunity to discover the material facts that New GM did not disclose and/or intentionally concealed. Old GM's fraud, fraudulent concealment and fraudulent non-disclosure were all components of the subject incidents of the Named Plaintiffs. Because New GM acquired knowledge of Old GM's activities and the defective ignition switch via the minds of the employees, officers, managers, books and records obtained and/or acquired as a result of the June 26, 2009 Amended and Restated Master Sale and Purchase Agreement and subsequent Sale Order, New GM is expressly liable to Named Plaintiffs. Further, the duties of Old GM are part of the foundation for the liability acquired by New GM.
- 121. Independent of any failures by Old GM as described herein, between July 10, 2009 and March 2014, New GM breached its duties to the Named Plaintiffs by failing to disclose knowledge of the defective ignition switch to Named Plaintiffs.
- 122. New GM had a duty to disclose the facts to the Named Plaintiffs and New GM knew: (1) that the Named Plaintiffs were ignorant of the material facts that New GM did not disclose and/or intentionally concealed; and (2) the Named Plaintiffs did not have an equal

09-50026em914 PAC 12326-1MFFiled 07/4341488Enterpel 07/31/14411c24j2934 Exhibit A - Motion Pa 39 of 55

opportunity to discover the material facts that New GM did not disclose and/or intentionally

concealed.

123. By failing to disclose these material facts, New GM intended to induce the Named

Plaintiffs to take some action or refrain from acting.

124. The Named Plaintiffs relied on New GM's non-disclosure and they were injured

as a result of acting without knowledge of the undisclosed facts.

VII. <u>DAMAGES</u>

125. The Named Plaintiffs pray for damages against the Defendant in a sum of money

in excess of the jurisdictional amount of Seventy-Five Thousand Dollars (\$75,000.00) plus costs

and any other such other relief to be deemed just and equitable to which they are entitled.

VIII. JURY DEMAND

126. The Named Plaintiffs request a trial by jury.

PRAYER

For the foregoing reasons, Named Plaintiffs pray that the Defendant be cited to appear

and answer herein, and that upon a final hearing of the cause, judgment be entered for the each

Plaintiff against Defendant for actual damages, as alleged, and exemplary damages; together

with pre-judgment interest (from the date of injury through the date of judgment) at the

maximum rate allowed by law; post-judgment interest at the legal rate, costs of court; and such

other and further relief to which Named Plaintiffs may be entitled at law or in equity.

Respectfully Submitted,

HILLIARD MUÑOZ GONZALES LLP

By: /s/ Robert C. Hilliard

Robert C. Hilliard

State Bar No. 09677700

-33-

Federal ID No. 5912 bobh@hmglawfirm.com Rudy Gonzales, Jr. State Bar No. 08121700 Federal ID No. 1896 rudyg@hmglawfirm.com Catherine D. Tobin State Bar No. 24013642 Federal ID No. 25316 catherine@hmglawfirm.com Marion Reilly Texas Bar No. 24079195 Federal ID No. 1357491 marion@hmglawfirm.com

719 S. Shoreline Boulevard, Suite 500 Corpus Christi, TX 78401 Telephone No.: (361) 882-1612 Facsimile No.: (361) 882-3015

-and-

By: /s/ Thomas J. Henry

Thomas J. Henry State Bar No. 09484210 Federal ID No. 12980 tjh@tjhlaw.com Curtis W. Fitzgerald, II State Bar No. 24012626 Federal ID No. 24980 cfitzgerald@tjhlaw.com

THOMAS J. HENRY INJURY ATTORNEYS

521 Starr St.

Corpus Christi, Texas 78401 Telephone No.: (361) 985-0600 Facsimile No.: (361) 985-0601

ATTORNEYS FOR PLAINTIFFS

09-50026em914 Proc 0.2326-1MFFiled 0.7/121/1488Enternel 07/131/114411-24j2936 Exhibit A - Mation HTB 15-5

No.	Name of Plaintiff(s)	Residency	Car Type	VIN#	Accident Date	Accident City/ State	U.S. District Court*
Dea	th						
1	Davis, Donna Individually, and as Representative of the Estate of Kendra Davis	Clyde, North Carolina	2000 Chevy Cavalier	1G1JC1246Y7406135	5/1/05	Waynesville, NC	Western District of North Carolina
2	Edwards, Pamela Individually, and as Representative of the Estate of Paul Adams	Jonesboro, Georgia	2008 Pontiac G6	1G2ZH58N774169761	3/18/08	Jackson, MS	Southern District of Mississippi
3	Goad, Lisa Individually, and as Representative of the Estate of Justin Wayne Goad	Dyer, Tennessee	2001 Chevy Impala	2G1WF55E719204482	11/5/07	Gibson County, TN	Western District of Tennessee
4	Gonzalez, Deborah Individually, and as Representative of the Estate of Roberto D. Gonzalez	Vineland, New Jersey	2008 Chevy Malibu	1G1ZH57B684200754	4/18/09	Vineland, NJ	District of New Jersey
5	Haseleu, Todd Individually, and as Representative of the Estate of Tiffany Lee Haseleu	Watertown, Wisconsin	2006 Chevy Cobalt	1G1AK15F867747145	6/11/09	Jefferson County, WI	Western District of Wisconsin
6	Hawkins, Carolyn Individually, and as Representative of the Estate of Tamia Williams	Montgomery, Alabama	2008 Chevy Malibu	1G1ZT58NX8G112964	7/6/08	Ponitiac, MI	Eastern District of Michigan
7	Herren, Gena Individually, and as Representative of the Estate of Morgan D'Nan Foster	Red Oak, Oklahoma	2006 Chevy Cobalt	1G1AK15FX67792510	12/13/06	Wilburton, OK	Eastern District of Oklahoma
8	Hicks, Jennie Individually, and as Representative of the Estate of Alphonso Hicks	Hephzibah, Georgia	2006 Chevy Impala	2G1WT55K369193924	9/15/08	Augusta, GA	Southern District of Georgia
9	Higgins, Sherell Individually, and as Representative of the Estate of Darneasha Brown	Calumet City, Illinois	2006 Chevy Cobalt	1G1AK55F167627873	9/3/05	Nashville, TN	Middle District of Tennessee
10	Johnson, Margaret Individually, and as Next Friend of Bryan Johnson, and as Representative of the Estate of Robert Brian Johnson	Fairfield, California	1997 Chevy Malibu	1G1NE52MXVY118238	6/26/01	Suisun, CA	Eastern District of California
11	Langley, Kim Individually, and as Representative of the Estate of Richard Bailey	Phoenix, Arizona	2007 Chevy Cobalt	1G1AL15F277100383	4/21/08	San Bernandino, CA	Central District of California

^{*}Named Plaintiffs state that but for the Order permitting direct filing into the Southern District of New York, they would have filed in the district courts listed in this column.

09-50026emg14 Proc 12326-1MFFiled Q7/131/14411F24j2937 Exhibit A - Motion Pg 42 of 55 EXHIBIT A

No	. Name of Plaintiff(s)	Residency	Car Type	VIN#	Accident Date	Accident City/ State	U.S. District Court
12	Lindsay, Kenneth Individually, and as Representative of the Estate of Rita Carol Lindsay	Altoona, Alabama	2006 Chevy Cobalt	1G1AL15F467777370	10/19/08	Attalla, AL	Northern District of Alabama
13	Moza, Joseph Individually, and as Representative of the Estate of Loretta Moza	Yale, Michigan	2006 Chevy HHR	3GNDA23D56S582078	8/4/08	Detroit, MI	Eastern District of Michigan
14	O'Shields, Mary Individually, and as Representative of the Estate of Brenda Inman	Myrtle Beach, South Carolina	2003 Chevy Impala		7/16/03	Dillon, SC	District of South Carolina
15	Powledge Colvin, Amber Individually, and as Representative of the Estate of Adam Powledge	Crosby, Texas	2004 Chevy Malibu	1G1NB52F34M598780	10/18/05	Texas City, TX	Southern District of Texas
16	Raniolo, Samuel Individually, and as Representative of the Estate of Christian Raniolo	Kings Mountain, North Carolina	2006 Chevy Cobalt	1G1AK55F767632009	10/10/07	Kings Mountain, NC	Western District of North Carolina
17	Swafford, Marshell Individually, and as Representative of the Estate of Corey Swafford	Wolfe City, Texas	2006 Chevy Cobalt	1G1AK55F067686784	11/5/05	Greenville, TX	Northern District of Texas
18	Tyler, Jacqueline Individually, and as Representative of the Estate of Altonio Tyler	Jackson, Mississippi	2008 Pontiac G6	1G2ZH58N774169761	3/18/08	Jackson, MS	Southern District of Mississippi
19	Vogt, William Individually, and as Representative of the Estate of Valerie Vogt	Hamlin, Pennsylvania	2006 Pontiac G6	1G2ZH158564186032	4/30/07	Wayne Lake Township, PA	Middle District of Pennsylvania
20	Wallace, Carla Individually, and as Representative of the Estate of Cory Wallace	Wyandotte, Oklahoma	2006 Chevy Cobalt	1G1AK15FX67838854	6/2/09	Miami, OK	Northern District of Oklahoma

09-50026emg14 Proc 12326-1MFFiled Q7/131/14411F24j298 Exhibit A - Motion Pg 43 of 55 EXHIBIT A

No.	Name of Plaintiff(s)	Residency	Car Type	VIN#	Accident Date	Accident City/ State	U.S. District Court
Inj	ury						
21	Anderson, Vangie	Clarksdale, Mississippi	2006 Chevy Cobalt	4T16E37K92U113110	12/17/08	Birmingham, AL	Northern District of Alabama
22	Banks, Isadore	Little Rock, Arkansas	2008 Chevy Cobalt	1G1AL58F887151763	1/1/09	Little Rock, AR	Eastern District of Arkansas
23	Baylor, Sandra D	Tallmadge, Ohio	2007 Chevy Cobalt		3/8/09	Austintown, OH	Southern District of Ohio
24	Bennett, Keith	South Williamsport, Pennsylvania	2009 Chevy Cobalt	1G1AK18H097197959	5/19/09	Montoursville, PA	Middle District of Pennsylvania
25	Berard, Brandy	Lake Charles, Louisiana	2005 Chevy Cobalt	1G1AK55F667640005	11/10/05	Welsh, LA	Western District of Louisiana
26	Bethel, Lisa	Fort Edward, New York	2007 Chevy HHR		6/1/07	, NY	
27	Bond, Dalena	Saucier, Mississippi	2005 Chevy Cobalt	1G1AK52F957512649	4/10/06	Saucier, MS	Southern District of Mississippi
28	Bonito, Kathleen	Downingtown, Pennsylvania	2006 Saturn Ion	1G8AJ55F06Z188481	5/6/08	East Whiteland Township, PA	Eastern District of Pennsylvania
29	Braxton, Linda	Taylor, Michigan	2007 Saturn Ion	1G8AJ55F27Z122404	10/8/08	Westland, MI	Eastern District of Michigan
30	Brooks, Joseph	Applevalley, Minnesota	2007 Chevy Cobalt		5/26/08	Minneapolis, MN	District of Minnesota
31	Brooks, Rose	Louisville, Kentucky	2005 Saturn Ion	1E8AL652535Z166410	11/6/08	Louisville, KY	Western District of Kentucky

09-50026emg14 Proc 12326-1MFFiled Q7/131/14411F24j2939 Exhibit A - Motion Pg 44 of 55 EXHIBIT A

No.	Name of Plaintiff(s)	Residency	Car Type	VIN#	Accident Date	Accident City/ State	U.S. District Court
32	Brown, Cathalina	University Park, Illinois	2005 Chevy Cobalt	1G1AL14F457616906	5/1/08	Orland Park, IL	Northern District of Illinois
33	Buckley, Amanda	Tulsa, Oklahoma	2004 Saturn Ion	1G8AG52F240114785	6/30/07	Tulsa, OK	Northern District of Oklahoma
34	Bueno, John	Lake Balboa, California	2008 Chevy Cobalt	Rental Vehicle VIN not recorded on police report	2/20/08	Sherman Oaks, CA	Central District of California
35	Bueno, Lisa	Lake Balboa, California	2008 Chevy Cobalt	Rental Vehicle VIN not recorded on police report	2/20/08	Sherman Oaks, CA	Central District of California
36	Burns, Angela	Nashville, Tennessee	2006 Chevy Cobalt	1G1AK15F467663646	4/14/06	Whitesburg, KY	Eastern District of Kentucky
37	Burton, Shari	Prattville, Alabama	2006 Chevy Malibu		1/1/06	,	
38	Caldwell, Connell	Rialto, California	2006 Saturn Ion	1G8AJ58F4967163305	6/23/09	Las Vegas, NV	District of Nevada
39	Carter, Nicole	Fairfield, California	2007 Chevy HHR		10/20/07	Lake County, CA	Northern District of California
40	Chandler, Dessie	Birmingham, Alabama	2006 Saturn Ion and 2009 Chevy Cobolt	1G1As58H397170890	4/1/08	Birmingham, AL	Northern District of Alabama
41	Collins, Billy V.	Mansfield, Ohio	2006 Chevy Cobalt	1G1AK55F667607361	2/23/08	Ontario, OH	Northern District of Ohio
42	Curry, Annie	Hyattsville, Maryland	2004 Chevy Malibu	1G1ZT64834F232539	7/25/08	Washington, DC	District of Columbia

09-50026emg14 Proc 12326-1MFFiled Q7/121/1488Enterpel 07/131/1411F24j2940 Exhibit A - Motion Pg 45 of 55 EXHIBIT A

No.	Name of Plaintiff(s)	Residency	Car Type	VIN#	Accident Date	Accident City/ State	U.S. District Court
43	Curry, Jacqueline	Upper Marlboro, Maryland	2004 Chevy Malibu		7/25/08	Washington, DC	District of Columbia
44	Cuthbertson, Ruth	Washington, District of Columbia	2008 Saturn Sky		7/28/08	Washington, DC	District of Columbia
45	Davis, Veronica	Burton, Michigan	2007 Chevy HHR	3GNDA23D465650032	9/16/07	Grand Blanc, MI	Eastern District of Michigan
46	Deforest, Gayla	Venus, Texas	2007 Chevy Cobalt	1G1AL55F877173619	5/1/08	Alvarado, TX	Northern District of Texas
47	Delhommer, Michelle	Prairieville, Louisiana	2008 Chevy Cobalt	1G1AK18F687224026	8/2/08	Prairieville, LA	Middle District of Louisiana
48	Delhommer, Michelle Individually, and as Next Friend of Justice Delhommer	Prairieville, Louisiana	2008 Chevy Cobalt	1G1AK18F687224026	8/2/08	Praireville, LA	Middle District of Louisiana
49	Delhommer, Michelle Individually, and as Next Friend of Justin Kyle	Prairieville, Louisiana	2008 Chevy Cobalt	1G1AK18F687224026	8/2/08	Prairieville, LA	Middle District of Louisiana
50	Deming, Michael	Flint, Michigan	2007 Chevy Cobalt	1G1AL55F577379514	11/7/07	Fayetteville, NC	Eastern District of North Carolina
51	Doindis Jr., Peter	Cleveland, Ohio	2008 Saturn Sky	1g8mb35bx8y100427	4/28/08	Canton, OH	Northern District of Ohio
52	Duckett, Raymond	Charlotte, North Carolina	2005 Chevy Cobalt	1G1AK12F557661892	4/26/08	Pittsburgh, PA	Western District of Pennsylvania
53	Edmonson, Kesha	Denver, Virginia	2006 Chevy Cobalt	1G1AK15FX67701381	1/1/06	Williamsburg, VA	Eastern District of Virginia

09-50026emg14 Proc 12326-1MFFiled Q7/131/14411F24j2911 Exhibit A - Motion Pg 46 of 55 EXHIBIT A

No.	Name of Plaintiff(s)	Residency	Car Type	VIN#	Accident Date	Accident City/ State	U.S. District Court
54	Edwards, Shiza	Millbrook, Alabama	2007 Chevy Cobalt		1/1/09	Montgomery, AL	Middle District of Alabama
55	Enzor, Marc	Tucson, Arizona	2005 Chevy Cobalt		1/1/06	,	
56	Ferdarko, Jacqueline	Lorian, Ohio	2004 Saturn Ion	1G8AN12F34Z200735	10/29/04	Lorain, OH	Northern District of Ohio
57	Ferrell, Tabatha	Chapmanville, West Virginia	2005 Chevy Cobalt	1G1AL12F757663818	8/5/08	Logan, WV	Southern District of West Virginia
58	Fish, Robert	Mulberry, Florida	2006 Pontiac Solstice	1g2mb35b26y113454	8/5/08	Tallahassee, FL	Northern District of Florida
59	Fleming, Jessica	Longview, Texas	2008 Chevy Cobalt		6/2/09	,	
60	Garza, Rosy E	Corpus Christi, Texas	2007 Chevy Cobalt		4/16/08	Gregory, TX	Southern District of Texas
61	Gaston Jr, Darryl R	Lexington, South Carolina	2003 Chevy Impala	2G1WH52K239421638	1/1/05	Jacksonville, AL	Northern District of Alabama
62	Gibbs, Santoria	Auburn, Alabama	2007 Saturn Ion	1G8AJ58F872199895	7/15/08	Montgomery, AL	Middle District of Alabama
63	Gillespie, Robert	London, Ohio	2007 Chevy HHR	3GNDA23D47S558212	11/1/07	London, OH	Southern District of Ohio
64	Gordon, Catherine	Algonac, Michigan	2005 Chevy Cobalt	1G1AL52F457511552	12/4/06	Port Huron, MI	Eastern District of Michigan

09-50026emg14 Proc 12326-1MFFiled Q7/131/1488Enterpel 07/131/1411F24j2912 Exhibit A - Motion Pg 47 of 55 EXHIBIT A

No.	Name of Plaintiff(s)	Residency	Car Type	VIN#	Accident Date	Accident City/ State	U.S. District Court
65	Grooms, Stephanie	Watertown, Tennessee	2007 Chevy HHR	3GNDA23P97S570706	10/21/08	Lebanon, TN	Middle District of Tennessee
66	Gross, Kevin D.	Glen Burnie, Maryland	2005 Chevy Cobalt	1G1AK12F557581332	6/22/08	Easton, MD	District of Maryland
67	Groves, Michelle	Independence, Missouri	2006 Chevy Cobalt	1G1AK15F167645122	4/21/09	Kansas City, MO	Western District of Missouri
68	Hairston, John T	Eden, North Carolina	2006 Saturn Ion	21GBAJ55RXZ12226	10/27/06	Perth Amboy, NJ	District of New Jersey
69	Haislah, Robert	Rome, Ohio	2006 Chevy Cobalt		6/1/07	Clevand, OH	Northern District of Ohio
70	Hamilton, Donnie	Fayetteville, North Carolina	2006 Chevy Cobalt	1G1AL15F177266118	11/14/08	Benson, NC	Eastern District of North Carolina
71	Harris, Charlesa	Westville, Oklahoma	2008 Chevy Cobalt	1G1AK18F087164132	9/23/08	Watts, OK	Eastern District of Oklahoma
72	Hemminger, Deana	Enigma, Georgia	2005 Chevy Cobalt	Not available	4/1/05	Chester, GA	Southern District of Georgia
73	Henley, Robert	Tomball, Texas	2005 Chevy Malibu		5/15/05	Houston, TX	Southern District of Texas
74	Higgins, Sherell	Calumet City, Illinois	2006 Chevy Cobalt	1G1AK55F167627873	9/3/05	Nashville, TN	Middle District of Tennessee
75	Hill, Roderick	Pearl, Mississippi	2006 Saturn Ion	1G8AJ55FX62110841	2/3/07	Yazoo, MS	Southern District of Mississippi

09-50026emg14 Proc 12326-1MFFiled Q7/131/1488Enterpel 07/131/1411F24j2913 Exhibit A - Motion Pg 48 of 55 EXHIBIT A

No.	Name of Plaintiff(s)	Residency	Car Type	VIN#	Accident Date	Accident City/ State	U.S. District Court
76	Hillman, Diana	Madison, Wisconsin	2006 Pontiac Grand Am	2G2WP552561147106	8/1/08	Madison, WI	Western District of Wisconsin
77	Honeycutt, Sammeeka	Los Angelos, California	2006 Chevy Cobalt	1G1AL55F767810529	11/25/07	West LA, CA	Central District of California
78	Howard, Tanya	Mobile, Alabama	2005 Chevy Malibu	1g1nd52f35m185517	1/1/08	Creola, AL	Southern District of Alabama
79	Hultgren, Erik	Menifee, California	2003 Saturn Ion	1g8ak52f13z143238	3/17/04	Riverside County, CA	Central District of California
80	James, Gwendolyn	Detroit, Michigan	2006 Chevy Cobalt		4/1/06	Troy, MI	Eastern District of Michigan
81	Jennings, Robert	Indianapolis, Indiana	2007 Saturn Ion		1/14/09	Indianapolis, IN	Southern District of Indiana
82	Johndro, Jason	Lorian, Ohio	2008 Chevy Cobalt	1g1ak18f387263589	3/1/09	Dallas, TX	Northern District of Texas
83	Johnson, Kara	Oswego, Illinois	2006 Saturn Ion	1g8aj55fx6z171364	11/20/07	Oswego, IL	Northern District of Illinois
84	Kage, Gloria	Baltimore, Maryland	2005 Chevy Cobalt		11/27/05	Hanover, MD	District of Maryland
85	Kalilou, Rasheda	Greensboro, North Carolina	2006 Chevy Cobalt		7/27/08	Gulfport, MS	Southern District of Mississippi
86	Keller, William F.	White Lake, Michigan	2004 Saturn Ion	1G8AY12P94Z231617	1/5/05	Bloomfield Township, MI	Eastern District of Michigan

09-50026emg14 Proc 12326-1MFFiled Q7/131/1488Enterpel 07/131/1411F24j2914 Exhibit A - Motion Pg 49 of 55 EXHIBIT A

No.	Name of Plaintiff(s)	Residency	Car Type	VIN#	Accident Date	Accident City/ State	U.S. District Court
87	Kichar, Karen	Webster, Massachusetts	2005 Chevy Cobalt	1G1AK54F357608404	7/25/08	Webster, MA	District of Massachusetts
88	Leblanc, Nachel	New Bedford, Massachusetts	2004 Saturn Ion	1G8AG52F14Z151911	1/1/05	New Bedford, MA	District of Massachusetts
89	LeDay, Gilbert	Baton Rouge, Louisiana	2006 Chevy Cobalt		1/28/08	Baton Rouge, LA	Middle District of Louisiana
90	Lee, Wanda	Dothan, Alabama	2008 Pontiac G6	1G2ZH57NX84134778	11/2/08	Marianna, FL	Northern District of Florida
91	Leonard, Janeshea	Ruston, Louisiana	2005 Chevy Cobalt	1G1AK52F057602658	1/1/09	Ruston, LA	Western District of Louisiana
92	Lichtenwalner, Pamela	Stinson Beach, California	2004 Saturn Ion	1G8AZ54F34Z155269	1/16/07	Stinson Beach, CA	Northern District of California
93	Lockhart, Marjorie	Monroe, Michigan	2003 Saturn Ion	1G8AL52F737204220	10/20/03	Frenchtown Twp, MI	Eastern District of Michigan
94	Lopez, Kimberly	La Jara, Colorado	2007 Chevy Cobalt	1G1AK15F477413437	3/8/09	Denver, CO	District of Colorado
95	Love, Mark	Gary, Indiana	2006 Chevy Cobalt	1G1AL15F367689510	4/1/07	Holbert, ID	District of Idaho
96	Lynn, Kenneth A.	Cincinnati, Ohio	2006 Chevy Malibu LS	1GT51F96F300100	7/14/08	Cincinnati, OH	Southern District of Ohio
97	Maclin, Justin	Warren, Michigan	2006 Chevy Cobalt		3/22/09	Detroit, MI	Eastern District of Michigan

09-50026emg14 Proc 12326-1MFFiled Q7/131/1488Enterpel 07/131/1411F24j2915 Exhibit A - Motion Pg 50 of 55 EXHIBIT A

No.	Name of Plaintiff(s)	Residency	Car Type	VIN#	Accident Date	Accident City/ State	U.S. District Court
98	McCloud, Patricia	Burkburnett, Texas	2005 Chevy Cobalt		11/4/06	Fargo, ND	District of North Dakota
99	Mency, Eileen	Boston, Massachusetts	2006 Chevy HHR	3GNDA23P56S524627	7/3/08	Dorchester, MA	District of Massachusetts
100	Moindi Wycliffe	San Jose, California	2005 Chevy Cobalt		3/1/09	, CA	Northern District of California
101	Moore, Justin	Gaylord, Michigan	2007 Chevy Cobalt		7/1/07	Almont, Lapeer County, MI	Eastern District of Michigan
102	Myers, Diane	Daytona Beach, Florida	2003 Saturn Ion	1G8A652F93Z102725	2/29/08	Port Orange, FL	Middle District of Florida
103	Owens, Janice	Lansing, Michigan	2005 Chevy Malibu	1G1ZT54885F162371	1/16/09	Lansing, MI	Western District of Michigan
104	Pearce, Kenneth	Mustang, Oklahoma	2004 Saturn Ion	1G8AZ52F54Z127640	4/1/05	Ada, OK	Eastern District of Oklahoma
105	Peete, Getta	St. Louis, Missouri	2006 Pontiac G6		5/10/07	St.Louis, MO	Eastern District of Missouri
106	Peoples, Earlesha	Cincinnati, Ohio	2007 Chevy Cobalt		11/1/07	Cincinnati, OH	Southern District of Ohio
107	Peterson, Ranae	Hortonville, Wisconsin	2007 Pontiac G5	1G2ZG58N274151638	6/30/09	Appleton, WI	Eastern District of Wisconsin
108	Polomsky, John	North Ridge Ville, Ohio	2008 Chevy HHR	3GNDA13D185607782	2/1/09	North Ridgeville, OH	Northern District of Ohio

09-50026emg14 Proc 12326-1MFFiled Q7/131/1488Enterpel 07/131/1411F24j2916 Exhibit A - Motion Pg 51 of 55 EXHIBIT A

No.	Name of Plaintiff(s)	Residency	Car Type	VIN#	Accident Date	Accident City/ State	U.S. District Court
109	Powell, Sharon	Glenwood, Illinois	2005 Chevy Cobalt	1G1AL14F457616906	5/21/08	Orland Park, IL	Northern District of Illinois
110	Pylar, Shirley	Clinton Township, Michigan	2006 Chevy HHR	3GNDA23D56S582078	8/4/08	Clinton Township, MI	Eastern District of Michigan
111	Robbins, Justin	Fairborn, Ohio	2008 Chevy HHR	3GNDA23D28S541751	10/1/08	Fairborn, OH	Southern District of Ohio
112	Rodgers, Dailene	Euclid, Ohio	2005 Chevy Cobalt	1G1AL14F957657788	6/6/07	Euclid, OH	Northern District of Ohio
113	Rodriguez, Rafael	Vineland, New Jersey	2003 Saturn Ion	1G8AL52F33Z186749	4/24/09	Vineland, NJ	District of New Jersey
114	Rooney, Richard	Kernville, California	2008 Chevy HHR		10/4/08	Worford Heights, CA	Eastern District of California
115	Roura, Samara	Mission, Texas	2006 Chevy Cobalt	1G1AK55F567840924	10/20/08	Pharr, TX	Southern District of Texas
116	Santiago, Carla	Vineland, New Jersey	2003 Saturn Ion	1G8AL52F33Z186749	4/24/09	Vineland, NJ	District of New Jersey
117	Scroggins, Deborah	Brooklyn, New York	2007 Chevy Cobalt	1G1AK15F477302645	12/12/07	Kings, NY	Eastern District of New York
118	Scroggins, Deborah	Brooklyn, New York	2007 Chevy Cobalt	1G1AK15F477302645	3/27/09	Brooklyn, NY	Eastern District of New York
119	Shinko, Patricia	Pittston, Pennsylvania	2008 Chevy HHR		6/1/07	Edwardsville, PA	Middle District of Pennsylvania

09-50026emg14 Proc 12726-1MFFiled Q7/131/14411F24j2917 Exhibit A - Motion Pg 52 of 55 EXHIBIT A

No. Name of Plaintiff(s)	Residency	Car Type	VIN#	Accident Date	Accident City/ State	U.S. District Court
120 Shipman, Deidra	Chadbourn, North Carolina	2008 Chevy HHR	3GNDA23D785530633	10/26/07	Whiteville, NC	Eastern District of North Carolina
121 Sims, Rodney	Waldoff, Maryland	2008 Saturn Sky		9/21/08	Washington, DC	District of Columbia
122 Slaughter, Kimberly	Jackson, Mississippi	2006 Chevy Cobalt	1G1AK55F177402712	1/17/09	Jackson, MS	Southern District of Mississippi
123 Small, Clara	Columbus, Georgia	2006 Chevy HHR	3GNDA13D86S573909	2/13/07	Columbus, GA	Middle District of Georgia
124 Small, Kenneth	Columbus, Ohio	2005 Chevy Malibu		12/24/08	Cleveland, OH	Northern District of Ohio
125 Smith, George E.	Westerville, Ohio	2005 Chevy Cobalt		6/5/07	Columbus, OH	Southern District of Ohio
126 Snyder, Anthony	Bloomsburg, Pennsylvania	2003 Saturn Ion	1G8AJ52F93Z136606	12/28/08	Berwick, PA	Middle District of Pennsylvania
127 Solomon, Jerald	Celveland, Ohio	2004 Chevy Malibu		9/1/06	Cleveland, OH	Northern District of Ohio
128 Sorrells, Rickey	Lansing, Michigan	2008 Chevy HHR		5/25/08	Olivet, MI	Western District of Michigan
129 Spencer, Christina	Madison, Georgia	2007 Chevy Cobalt		1/9/08	Greensboro, GA	Middle District of Georgia
130 Stanley, Deborah	Clintwood, Virginia	2007 Chevy Cobalt	1G1AK55F177403858	10/25/07	Big Branch, VA	Western District of Virginia

09-50026emg14 Proc 12726-1MFFiled Q7/131/14411F24j2918 Exhibit A - Motion Pg 53 of 55 EXHIBIT A

No.	. Name of Plaintiff(s)	Residency	Car Type	VIN#	Accident Date	Accident City/ State	U.S. District Court
131	Stanley, Glenn	Clintwood, Virginia	2007 Chevy Cobalt	1G1AK55F177403858	10/25/07	Big Branch, VA	Western District of Virginia
132	Starks, Sharm	Cleveland Heights, Ohio	2007 Chevy Cobalt		1/27/07	Cleveland, OH	Northern District of Ohio
133	Stevens, Cheryl	Brooksville, Florida	2006 Saturn Ion	K250628384430	3/8/08	San Antonio, FL	Middle District of Florida
134	Strauss, Alaina	Aurora, Colorado	2003 Saturn Ion		10/1/03	Lakewood, CO	District of Colorado
135	Surbeck, Kally	Cheyenne, Wyoming	2007 Chevy HHR	3GNDA23PX78536435	6/21/09	Lusk, WY	District of Wyoming
136	Taylor, Kenya	Birmingham, Alabama	2006 Chevy Cobalt	1G1AK55F967757626	1/1/08	Tuscaloosa, AL	Northern District of Alabama
137	Thomas, Frank	Decatur, Alabama	2006 Chevy Malibu	1G1ZT548X4F223511	3/10/09	Decatur, AL	Northern District of Alabama
138	Thomison, Teresa	Spring, Texas	2007 Chevy Cobalt	1G1AL15F177361892	1/12/09	Houston, TX	Southern District of Texas
139	Torres, Aleni	Defiance, Ohio	2005 Chevy Cobalt	1G1AL52F157564483	6/29/06	Napoleon, OH	Northern District of Ohio
140	Torres, Daniel	Defiance, Ohio	2005 Chevy Cobalt	1G1AL52F157564483	6/29/06	Napoleon, OH	Northern District of Ohio
141	Vasquez, Hilda	Quail Valley, California	2007 Saturn Ion	1G8AJ55F47Z124610	5/21/09	Wildomar, CA	Central District of California

09-50026emg14 Proc 12726-1MFFiled Q7/131/14411F24j2919 Exhibit A - Motion Pg 54 of 55 EXHIBIT A

No.	Name of Plaintiff(s)	Residency	Car Type	VIN#	Accident Date	Accident City/ State	U.S. District Court
142	Vega-Torres, Omaira	Defiance, Ohio	2005 Chevy Cobalt	1G1AL52F157564483	6/29/06	Napoleon, OH	Northern District of Ohio
143	Venable, Houston	Halifax, Virginia	2008 Chevy Cobalt	1G1AL18F287199980	2/8/09	Halifax, VA	Western District of Virginia
144	Washington, Myra	Flint, Michigan	2006 Saturn Ion	1G8AJ55FX6Z103923	6/3/09	Lakeville, MI	Eastern District of Michigan
145	Watkins, Diana	Blytheville, Arkansas	2003 Saturn Ion		3/12/03	Satillo, MS	Northern District of Mississippi
146	Watkins, Lester	Blythevill, Arkansas	2003 Saturn Ion		3/12/03	Saltillo, MS	Northern District of Mississippi
147	Wellington, James	Mt. Olive, North Carolina	2009 Chevy Malibu	1G1ZH57BX9F112084	1/22/09	Mount Olive, NC	Eastern District of North Carolina
148	Weston, Rhonda	Depew, New York	2006 Saturn Ion	1G8AJ55F46Z148579	1/31/06	,	
149	White, Virginia	Indianapolis, Indiana	2005 Chevy Cobalt	1G1AK52F657633011	10/16/06	Indianapolis, IN	Southern District of Indiana
150	Williams, Alexander	Houston, Texas	2007 Chevy Cobalt	1G1AL55F677324330	12/1/07	Wolflake, IN	Northern District of Indiana
151	Williams, Terrell	Poplar Bluff, Missouri	2006 Chevy Cobalt	1G1Ak55F167627873	9/3/05	Decatur, GA	Northern District of Georgia
152	Willis-Singh, Tanya	Darby, Pennsylvania	2007 Pontiac Solstice	1G2MB35B38Y107410	3/20/08	Darby, PA	Eastern District of Pennsylvania

09-50026emg14 Proc 12326-1MFFiled Q7/131/14411F24j2950 Exhibit A - Motion Pg 55 of 55 EXHIBIT A

No.	Name of Plaintiff(s)	Residency	Car Type	VIN#	Accident Date	Accident City/ State	U.S. District Court
153	Wilson, Alexis	Montgomery, Alabama	2008 Chevy Malibu	1G1ZT58NX8G112964	7/6/08	Pontiac, MI	Eastern District of Michigan
154	Wilson, Johnny	Taylorsville, Mississippi	2008 Chevy HHR	3GNDA23D18S523810	1/30/09	Taylorsville, MS	Southern District of Mississippi
155	Wright, Jacqueline	Washington, District of Columbia	2006 Chevy HHR	3GNDA23P96S515588	5/23/08	Washington, DC	District of Columbia
156	Wyche, Vinessa	Poughkeepsie, New York	2004 Saturn Ion	1G8AJ527X42113269	9/3/07	Poughkeepsie, NY	Southern District of New York